

Name of Inspector: Mark A. Randazzo/O'Brien & Gere Engineers

Signature: 

Date of Inspection: January 11, 2017

Time of Inspection: 1430 hrs

1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.

Key: Satisfactory – S Not Applicable – NA See Comment Section – C	AREAS SUBJECT TO INSPECTION		Additional Comments
	Southside of Bldg.	Northside of Bldg.	
Are there any hoses or signs of washing of vehicles or equipment (e.g., floats) outside?	C	S	At the time of the inspection a truck was being washed in the garage bay; however, the garage bay oil/water separator was plugged with sand and wash water was noted flowing outside the garage. Personnel were notified to cease operations and a vac truck was used to clean out the chambers, while the inspector was on-site.
Interview one employee to assess compliance with this policy?			Name: On-site NYRA employee
Is there a posting inside the building notifying workers of proper process wastewater management?	S	S	Sign is posted at entrance door leading to office, lavatory, and breakroom.
Are there postings outside the building notifying workers of proper process wastewater management?	S	S	Posted outside of garage bays on both sides of building.
Other issues:			

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204-5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH – (718) 641-4700 (ASK OPERATOR) OR AQUEDUCT MAIN SECURITY AT (718) 659-3511.

