


Name of Inspector: Frank Donroe Signature: 

Date of Inspection: 3-22-19 Time inspection started: 2pm

**1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.**

AREAS SUBJECT TO INSPECTION		Additional Comments
Southside of Bldg.	Northside of Bldg.	
<b>Process Wastewater Management</b>		
Are there any hoses or signs of washing of vehicles or equipment (e.g. floats) outside?	S	S
Interview one employee to assess compliance with this policy?		Name: Rob xxxx
Is there a posting inside the building notifying workers of proper process waste water management?	S	S
Are there posting outside the building notifying workers of proper process wastewater management	S	S

**Other Issues: Pump #2 is being repaired.**

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204-5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641.7400 OR AQUEDUCT MAIN SECURITY AT (718)659.3511